# RESTORING? FRANK'S FOLLY (OR NOT)



## FREDDI... "NOT EVEN WITH A CADDY 500 !!"



GMS SOLUTION TO BAD BONDING
PROBABLY BY THE DEALER




#### LOOKS LIKE A SCAB?



WHERE IS MY LIESURE SUIT?



#### **ANOTHER WARNING**



A LITTLE LOUD, YOU THINK?



**NICE ALCOAS** 



#### THE ORIGINAL THROUGH THE BUMPER HITCH



### LATER MODELS USED STAMPED FRAMES



• NICE VIEW, CAN CHECK FOR TIRE WEAR WHILE MOVING



**REPLACED THE WHOLE FLOOR** 



FIRST LAYER ¾ CDX




FINAL LAYER, ¼" BONDED WITH URATHANE



HONDA SEATS, LINCOLN POWER SEAT BASE



**FUEL LINE OUTSIDE FRAME** 



**SS BRAKE LINES** 



**STEEL FUEL LINE TO OUTSIDE** 

**FUEL LINE TO OUTSIDE** 







#### **NOT A CAT BUT A CADDY**



**WOULD YOU EAT HERE** 




**THAT'S BETTER** 



**MICROWAVE INSTALL** 

**FULL EXTN. DRAWER SLIDES** 





**DOMETIC 2 WAY** 



1 IN CHIMNEY CLEARANCE



DA,DA,DA



NOT ROCKECT SCIENCE MAYBE 20-20




**ZIPPY SIDE LIGHTS** 





**MANNY'S COOLER RECCOMENDATION** 



A LITTLE LOUD, YOU THINK?